## vDrive<sup>QL</sup> Firmware Update 002

Before updating the firmware, check the existing version by executing the toolkit VINFO command. If the existing version of VDRV is 2.03 or lower, FSYS is 2.01 or lower, or TKQL is 1.07 or lower, then this update applies.

After the update VINFO will show:

UDRU ∪2.05 FSYS ∪2.02 TKQL ∪1.08

To update the firmware please refer to the latest version of the vDriveQL user manual.

## Patch Notes 17/08/18

- Added VSTD/VSWAP status in VINFO.
- Added beep when vMap command executed.
- Fixed several edge case defects in address decoding.
- Fixed defect in the extended command handling whereby a command would time out if executed after an access to an empty vDrive.
- Added simulation of corrupt data on initial drive access as 'perfect' data was causing some applications to reject the cartridge image (notably The Pawn for save and restore).