

vDrive^{QL} Firmware Update 002.1

Before updating the firmware, check the existing version by executing the toolkit `VINFO` command. If the existing version of VDRV is 2.05 or lower, FSYS is 2.02 or lower, or TKQL is 1.07 or lower, then this update applies.

After the update `VINFO` will show:

```
VDRV v2.06  
FSYS v2.03  
TKQL v1.08
```

To update the firmware please refer to the latest version of the vDrive^{QL} user manual.

Patch Notes 21/08/18

- Changed behaviour of `TKOFF` to volatile. This means that the built-in toolkit will be disabled until `TKON` is executed or a power reset. Default behaviour is `TKON` after power on.
- Changed firmware to be compatible with version 2 of the SD Module hardware (green PCB).
Warning: *If a vDrive with the green PCB version of the SD module is reverted to a firmware version prior to 002.1 then erratic SD card behaviour will occur. vDrives with the Blue PCB version of the SD module are unaffected.*