

vDrive^{QL} Firmware Update 001

Before updating the firmware, check the existing version by executing the toolkit `VINFO` command. If the existing version of VDRV is 2.01 or lower, TKQL is 1.07, or lower, then this update applies.

After the update `VINFO` will show:

```
VDRV v2.02  
FSYS v2.01  
TKQL v1.08
```

To update the firmware please refer to the latest version of the vDrive^{QL} user manual.

Patch Notes 24/10/17

- Added format support for Sinclair AH, JS (USA version), Minerva v1.89 and v1.97.
- Have changed the error message wording from 'File in use' to 'Image currently assigned' to provide a clearer reason as to why a command cannot be completed. This affects the LD, MV and RM commands.
- Added the message 'SD Card initialised' after successful initialisation. Previously there was simply a return to the command prompt.
- Fixed a defect where, with the SD card removed and the built-in toolkit was enabled, the next drive was not being addressed.
- Some SD Cards take longer to format than the 30 seconds that was originally allowed for. This seems to affect cards with 2GB or less capacity. This is likely related to the speed (and age) of the card rather than capacity as newer 32GB cards format in about 12 seconds. The timeout has been doubled to over 60 seconds which should cover most cards.